The Shaw Frame House is a two story, 3 bay ide L shaped facade. The original siding has been covered with insul brick. The roof is gabled and it too has been replaced. The windows are two over two lights with a wooden comice and plain trim.

Two original corbeled chimneys are located within the facade.

INVENTORY FORM FOR STATE HISTORIC SITES SURVEY

NAME					
HISTORIC					
	ajor Shaw frame House				
AND/OR COMMON					
- Co	ollins Frame House				
LOCATION					
STREET & NUMBER					
Rt	. 220 South, .3 mile	South of Rawling	S		
CITY, TOWN	4 * 47		CON	GRESSIONAL DISTR	RICT
STATE	awlings X	VICINITY OF	COU	Sixth	
	aryland		0001	Allegany	
CLASSIFIC	ATION				
CATEGORY	OWNERSHIP	STATUS		PRES	ENT USE
DISTRICT	PUBLIC	OCCUPIED	_	_AGRICULTURE	MUSEUM
EBUILDING(S)	PRIVATE	UNOCCUPIED	_	_COMMERCIAL	PARK
STRUCTURE	вотн	WORK IN PROGRESS		_EDUCATIONAL	X PRIVATE RESID
SITE	PUBLIC ACQUISITION	ACCESSIBLE		_ENTERTAINMENT	
OBJECT	IN PROCESS	YES: RESTRICTED		_GOVERNMENT	SCIENTIFIC
	BEING CONSIDERED	YES: UNRESTRICTED		_INDUSTRIAL	TRANSPORTAT
		X _{NO}		_MILITARY	_OTHER:
NAME Wi	lbur Collins		Teleph	one #: 7	729-3532
STREET & NUMBER	O O				
	O. General Delivery				
CITY, TOWN	wlings X	VICINITY OF		Maryland	ip code 21557
LOCATION	OF LEGAL DESCR	IPTION	- * -		
				#: 454	
COURTHOUSE.	ETC 133	0	Folio	#: 85	
REGISTRY OF DEEDS,	Allegany County	Courthouse			
STREET & NUMBER	30 Washington St	reet.			
CITY, TOWN				STATE	
	Cumberland			Maryland	
REPRESEN	TATION IN EXIST	ING SURVEYS			
TITLE					
DATE		FEDERAL	STATE (COUNTYLOCAL	
DEPOSITORY FOR				LUCAL	
SURVEY RECORDS					
CITY, TOWN				STATE	

__EXCELLENT

_GOOD

FAIR

CONDITION

__DETERIORATED

__RUINS __UNEXPOSED CHECK ONE

__UNALTERED

CHECK ONE

__MOVED DATE_____

DESCRIBE THE PRESENT AND ORIGINAL (IF KNOWN) PHYSICAL APPEARANCE

The Collins frame house is located off Route 220 South near Rawlings, Allegany County on the west side of the road, three tenths of a mile South of Rawlings, along a small portion of old Route 220.

The house consists of a two story, three bay wide "I" shaped facade. A two story wing abuts the main block on the rear western side and forms the "I" of the structure. The building is a frame structure that has been covered with insul brick siding and is supported by a lew stone foundation with a plain water table. The roof of the structure is gabled including soffit, and is covered by replaced asphalt materials. Windows in the residence include double hung wooden sash frames with two-over-two lights, wooden cornice and plain trim. The main entrance is located on the front eastern face and exhibits the original verticle paneled door with plain trim. An end porch covers the front entrance and features a shed roof which is supported by square columns. Two corbeled brick chimneys, which are original, are located within the facade; one is located centrally to the main block and the other is located on the flush northern end of the main block.

The old frame house is tructurally fairly sound, however it is beginning to deteriorate and it has been somewhat altered.

	FS ca. 1850	BUIL DER/ARCH	·	
1900-	COMMUNICATIONS	INDUSTRYINVENTION	POLITICS/GOVERNMENT	OTHER (SPECIFY)
<u>V</u> 1800-1899	COMMERCE	EXPLORATION/SETTLEMENT	PHILOSOPHY	TRANSPORTATION
1700-1799	ART	ENGINEERING	MUSIC	THEATER
1600-1699	ARCHITECTURE	EDUCATION	MILITARY	SOCIAL/HUMANITARIAI
1500-1599	AGRICULTURE	ECONOMICS	LITERATURE	SCULPTURE
1400-1499	_ARCHEOLOGY-HISTORIC	CONSERVATION	_LAW	SCIENCE
PREHISTORIC	ARCHEOLOGY-PREHISTORIC	COMMUNITY PLANNING	_LANDSCAPE ARCHITECTURE	RELIGION
PERIOD	AF	REAS OF SIGNIFICANCE CH	ECK AND JUSTIFY BELOW	

: STATEMENT OF SIGNIFICANCE

The Major Shaw Frame House is one of four houses located on a property that at one time belonged to a Major in the Union Army. It is the simplest of the houses, having been built in the same style as many of the farm houses in Allegany County. During Major Shaw's lifetime, it was used as a wash house and a butcher house for the once prosperous farm.

The house is in fairly good condition but is deteriorating. The property now belonging to Wilbur Collins, has been renovated to a residence and is being leased to a small family.

^{1.} Interview with Mrs. Helen Hinkle, Treasurer of Allegany Committee of the Maryland Historical Trust 3/13/76

9 MAJOR BIBLIOGRAPHICAL REFERENCES

Allegany County Land Records, Cumberland, Maryland

CONTINUE	ON	SEPARATE	SHEET	IF	NECESSARY
----------	----	----------	-------	----	-----------

10 GEOGRAPHICAL DATA

ACREAGE OF NOMINATED PROPERTY 968.39 acres

VERBAL BOUNDARY DESCRIPTION

LIST ALL STATES AND COUNTIES FOR PROPERTIES OVERLAPPING STATE OR COUNTY BOUNDARIES

STATE

COUNTY

STATE

COUNTY

11 FORM PREPARED BY

NAME / TITLE

John E. Nelson, Program Coordinator of All	. Co. Historic Sites
ORGANIZATION	DATE
Allegany County Historic Sites Survey	7/6/76
STREET & NUMBER	TELEPHONE
10 Park Lane	689=8486
CITY OR TOWN	STATE
Frostburk	Marvland

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature, to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 Supplement.

The Survey and Inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

RETURN TO: Maryland Historical Trust

The Shaw House, 21 State Circle

Annapolis, Maryland 21401

(301) 267-1438

INVENIERY NO. AI-VI-B-018 L: ber-454
(/12/7/ Folio - 85
DATE: 6/23/16 968.39 Acres - MINGDINING: Drastic, moderate, minor
MAKE OF PROPERTY: Major Shaw Old France House
\sim
~) I
DIRECTION DWELLING FACES: <u>Fast</u>
MAME OF OWNER: Wilbur Collins 729-3532
ADDRESS: General Delivery Rawling P.O.
Rawlings, Maryland 21557
STORIES: 1() 2(1) 3() 4() 5() 6() BAYS: 1() 2() 3(1) 4() 5() 6() 7() ()
WINGS, ADDITIONS: Rear Wing - "L' Shaped
Dwelling Shape: (square, cross, rectangular)
WALL CONSTRUCTION:
(*) FRAME: Bevel, clapboard, weatherboard, wood shingles, board & batten (type?) () BRICK: Bond type- common, English, Flemish. Sketch variants. () STONE: Bond type- rubble, ashlar (random or regular), quoins-plain, rusticated () LOG () Other: Coverings I kill Brick
WALL FRATURES: BELT COURSE, PILASTELS, CTHERS Plain FOUNDATIONS: HIGH, TOWN BRICK, STONE WATER TABLE: NONE, PLAIN BEVELED, MOULDED BRICK
WINDOWS, TRIM, SHUTTERS: 1/1() 2/2(x) 6/6() 9/6() 9/9() other() pegged () nailed() wide () narrow () mitred () pediment (/)
ENTRANCE, DOORS: LOCATION: HARDWARE: original() replaced() FAN LIGHT, TRANSOM, SIDE LIGHTS, PLAIN Paneled, Verticle Horizontal Boards
CORNICE, BARGE, EAVES: (crown, fascia, coffit, bed) original() replaced() Rafter Ends, Modillions, Dentils, Frieze,
Architrave RCGF: GABLE FRONT, GABLE FLANK, HIF, SHED, LANGARD, GAMBREL, FLAT, EORNERS # MATERIAL: wood shingles, slate, tin, asphalf original() replaced()
FORCHES: SHAFE OF ROOF - shed() hip() gable()
CHIMBLES: NUMBER 1 PRICK() STONE() CORBLEED() original() replaced() LOCATION: Flush end() Inside end() (outside end() Central() Interior()
ARCHES: Door and window: Keystone, (lat) Cegmental, Semicircular
Use - Residence Dignificance - Arch Date Constructed - Mid 19th Condition - Deteriorated - fair

Key points regarding interior architecture.

1. Floor plan
No through hall--How many rooms long and deep?
Where is stairway? Straight or winding?

With through hall--Rooms on both sides? How many?


Rooms on one side only? How many?

Is stair in through hall?

Open or enclosed? Straight--one run. Straight--landing
How many? Curved.

If not in hall, where is stair?

- 2. Wall finish: plaster, paneled, board partition Note presence of chair rail, cornice, etc.
- 3. Fireplaces: How many? Parallel to walls or diagonal in corner?
 Mantels: wood--mouldings, pilasters, columns masonry--marble (what color?), brick
- 3. Doors: on the inside of exterior doors, note the presence of applied flush boards and their direction (diagonal, vertical, horizontal). In general are doors paneled or ledge or other?
- 4. Door and window trim: plain, architrave; fluted, reeded; pilasters
- 5. Kitchen: Where is original if extant or known (marked by very large fireplace)? Separate building; wing to principal dwelling; within principal dwelling? On which floor of any of the above?





A1-V1-B-018 Major Show Old Frame House Rt. 220 South .3 Mile S. of Rawlings John E. Nelson 6/23/76 Southwest



Major Shaw Old Frame House Al-U1-B-018 Rt. 220 South .3 Mile S. of Rawlings John E. Nelson 6/23/76 Southeast